












SID-IIsD

Rib Potentiometer Mounting Reference

Linear Pot Hook Orientation	Potentiometer Mounting Orientation	Potentiometer Collar Adjustment
<p>Shoulder Rib:</p> 	<p>Shoulder Rib:</p> 	<p>Collar Position for Shoulder Rib</p> 
<p>Upper Thorax Rib:</p> 	<p>Thorax Ribs and Upper Abdominal Rib:</p> 	<p>(4) Set Screw Detents Provided on Potentiometer Body for Each Position</p> 
<p>Mid Thorax Rib:</p> 		<p>Collar Position for Thorax Ribs and Abdomen Ribs</p> 
<p>Lower Thorax Rib:</p> 		
<p>Upper Abdominal Rib:</p> 	<p>Lower Abdominal Rib:</p> 	
<p>Lower Abdominal Rib:</p> 